



cdc

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

REGISTRATION APPLICATION OF: Fu et al.

Our File: 26-7 US

Serial No: 10/084,798

Group: 2828

Patent No: 6,859,470

Issued: Feb 22, 2005

Title: AIR TRENCH THAT LIMITS THERMAL COUPLING BETWEEN LASER AND LASER DRIVER

September 12, 2005

Commissioner for Patents  
P.O. Box 1450  
Alexandria, VA 22313-1450

Certificate  
SEP 22 2005  
of Correction

Dear Sir:

We respectfully request the correction of errors as set out in the attached Certificate of Correction. It is our understanding that, since these errors occurred in the United States Patent and Trademark Office, no fee is required.

The Commissioner is hereby authorized to charge any fees which may be required, or credit any overpayment, to Deposit Account 50-1465.

Respectfully,

Neil Teitelbaum  
Regn No: 38,793

Customer No: 24949

Teitelbaum & MacLean  
Registered Patent Agents Limited  
1187 Bank Street, Ste 201  
Ottawa, Ontario, K1S 3X7  
Canada

Tel: (613) 523 3784  
Fax: (613) 523 6799  
Email: [nt@patents.org](mailto:nt@patents.org)  
[www.patents.org](http://www.patents.org)

/mdb

SEP 22 2005

**UNITED STATES PATENT AND TRADEMARK OFFICE**

**CERTIFICATE OF CORRECTION**

**PATENT NO:** 6,859,470

**DATED:** February 22, 2005

**INVENTOR(S):** Fu et al.

It is certified that errors appear in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Col. 25, line 32, "modify" should read -- modify --

Col. 30, line 53, "subassembly 1165" should read -- subassembly 1105 --

Col. 36, line 22, "contact 3116" should read -- contact 3110 --

Col. 37, line 3, "nitrate (AIN)" should read -- nitrate (AIN) --

MAILING ADDRESS OF SENDER:

PATENT NO. 6,859,470

Teitelbaum & MacLean  
Registered Patent Agents Limited  
1187 Bank Street, Ste 201  
Ottawa, Ontario  
Canada  
K1S 3X7

Tel: (613) 523 3784  
Fax: (613) 523 6799  
Email: nt@patents.org  
www.patents.org

Form PTO 1050

SEP 22 2005